

# Radio observatory report and current LOFAR issues

Michiel Brentjens

Radio Observatory  
ASTRON, Dwingeloo, The Netherlands

LOFAR Status Meeting 20091111

ASTRON

- 1 Observatory status
- 2 Status of issues
- 3 Slow rise of HBA sensitivity
- 4 Observation queue

- CS030, CS021, CS006 not connected this week
- RS503 used for station calibration observations
- X/Y phase difference of 180 degrees on CS302 LBA
- No known electric fences at this moment
- list nodes are being phased out. All data recording on lsexxx nodes from now on
- lifs nodes will be phased out by November 30
- Estimated life time of observations on lse001–lse003: 6–8 weeks

SAS/MAC various experiments

TBB various experiments

Station stability & cal continuously cycling through all stations

observation181 L2009\_15696 PSRB1937+21 HBA (very good)

observation178 L2009\_15697 Tau A HBA (very good)

observation182 L2009\_15753 PSRB1937+21 HBA (bad: remote stations did not switch to 200 MHz clock)

observation180 L2009\_15758 Tau A LBA (very good)

- 1 Observatory status
- 2 Status of issues**
- 3 Slow rise of HBA sensitivity
- 4 Observation queue

# Bug list (SOLVED)

- HBAs take minutes to reach full sensitivity (Henri Meulman)
- Writing to new storage abysmally slow for cross correlation products (Jan David Mol)
- SAS/MAC and/or beamctl do not always switch RCU mode correctly (Ruud Overeem)

# Bug list ((almost) EXPLAINED)

- Timestamps of LofarStMan are beginning of integration, not middle.
- Signal paths of even RCUs can jump between a high and low state (LBL/LBH switch broken (by ESD?)). New RCU: ESD diode, and no trafo's. Needs more research. Switches are of same type as faulty HBA delay boards. Why only even RCUs: unexplained.
- Phase jumps in waveform generator test at 200 MHz clock (Eric Kooistra, Brentjens) Test observation in queue.
- Non-hermiticity in ACM blocks of intra-RSP board visibilities in waveform generator tests (Overeem, Kooistra, will be fixed in RSPDriver)
- HBA AC oscillations (Wijnholds)

# Bug list (OPEN)

- Discrete jumps in HBA power and RMS
- Occasional timestamp jumps of 1 in CS302/RSP0 data sent to CEP. Due to CRC errors? (Kooistra, Romein)
- Steps in delay w.r.t. Nancay
- TP variations/ionospheric absorption (Ger de Bruyn)
- AC oscillations Pandey (nobody working on this)
- AC dips (Michiel Brentjens, PSR group. Useful data taken in second psr busy week)



- 1 Observatory status
- 2 Status of issues
- 3 Slow rise of HBA sensitivity**
- 4 Observation queue

## Discovery and solution

- Two weeks ago HBA production stop due to defective test setup: found slow gain rise in lab tests
- Cause: no leakage path for DC charge on delay lines to ground. Charge leaks through switches, which take a long time
- Solution: future front ends have resistor from delay line to GND
- However, about **25 000** front ends already produced or even installed.

## Not possible now

- Put resistors on boards in field (cannot solder through water-proofing coating)
- Replace boards in field with boards that do have the resistor (Can our directors consider this?)

## Possible now

- Wait about 15 minutes to "warm up" the frontends before starting the observations.
- For fast switching observations that switch between LBA and HBA mode it must be made possible to switch on the bias voltages of LBA and HBA simultaneously. The RCU can be switched from mode to mode leaving the power of the LBA and HBA antennas on. This is always better to do to overcome warning up and cooling down effects during the observations.
- ...

- 1 Observatory status
- 2 Status of issues
- 3 Slow rise of HBA sensitivity
- 4 Observation queue**

# Observation queue

- Polarization busy week observations
- Station calibration observations