
"CS1" Status 11 July 2007

Menno Norden




Humidity & Temperature cycling test
 (95% Hum. and Temp. cycle between 25°C and 55°C)





HBA Tiles on CS010 (Y polarity)





HBA inter tile check of failing FE units (05 July 2007)

| T1 - 64X 1,6,13 | (3) |
|-------------------------|----------------|
| T1 - 65Y 4,16 | (2) |
| T2 - 66X 1,6,8,13,15 | (6) |
| T2 - 67Y 9,13,14,15 | (4) |
| T3 - 68X 1,11 | (2) |
| T3 - 69Y 5,7,9,10,15,16 | (6) |
| T4 - 70X 1,8,15 | (3) |
| T4 - 71Y 1,7,10,13,16 | (5) |
| T5 - 72X 5,11 | (2) |
| T5 - 73Y 4,11 | (2) |
| T6 - 74X 12,16 | (2) |
| T6 - 75Y 5,11,12,16 | (4) |
| total failing pol. | (41/192 = 21%) |



- Humidity & Temperature cycling test
 - Serious problems with GaAs switches (delay lines)!!
 - # 21% Failures found in the 6 Tiles
 - RF switches fail also in Climate Chamber(95% Hum and temp cycle between 25°C and 55°C)
 - Several circuit modifications have been tested but still failing switches

Alternative: CMOS switches, Different Manuf.



Digital board status

- RSP III boards
 - Remote update works
 - Lane between boards is not correct working
 - Next week we expect remaining RSPIII boards
- TBB boards
 - Debugging phase
 - This morning we received all boards





CEP/WAN news

- IP renumbering in Groningen
 - ₱ first or second week of August
 - One week offline



Roll-out news

- Two doors will be replaced CS001c (tomorrow)
 - Coating was sprayed on the wrong places
 - EMC gaskets are proper mounted
 - One fan will be replaced (damaged)



Roll-out news

- Bending experiment of plastic LBA pole
 On CS010 different poles are placed
- Replacement of the door locks (CS010 ready)
- Mowing of the "vegetation"



