"CS1" Status 11 Oct 2007

Menno Norden



HBA status

- FE board rework at Neways
 - Altenative switches are mechanically sensitive
 - Boards are not proper cleaned (some short circuits)
 - Boards need to be retested and coated
 - The humidity problem seems to be solved



HBA status

- ◆ 11 of the 12 coax cables where damaged
 - New cables are ordered and will be installed
 - One single element damaged (S29)




Status Effelsberg (GE001)

- Complete station on 19 September 2007
- RSP III boards
 - 24 boards are working
- TBB boards
 - 12 board are working (more testing needed)
- GPS signal reception improved
 - Low loss coax cable installed
 - GPS antenna 1 meter higher
- Remote SSH access available
- Airco units not in place (only two subracks)
- Preparation for stand alone mode (local processing)



Status Effelsberg (GE001)

1190220214 - Wed, 19 Sep 2007 16:43:34 +0000





Micro stations (16 \rightarrow 24)

- Four LCU's are installed (CS-10)
 - CS010C (subrack 0,1,2 with ring)
 - + CS030C (subrack 0, no ring)
 - + CS031C (subrack 1, no ring)
 - + CS032C (subrack 2, no ring)
- ◆ 12 micro stations at CS-10
 - \oplus Each station has four antennas (ring \rightarrow 16/ no ring \rightarrow 24)
- ◆ 12 micro stations at CS-1, 8 an 16
 - Each station has four antennas (with ring)



Status TBB boards

- Two TBB board available in CS-1 for test
 - Please test the TBB boards with astronomical data
 - We try to improve stability in firmware and drivers
 - Sometimes the boards/software is not responding



Visitors at NAA cabinet

