



## PL611 – Station report





- PL611 has been commisioned in October and since than is available for normal operations
- Station is nearly-100% operational





- LBA: all tiles OK
- HBA: tile no. 5
  broken power
  summator failure
- Tile no. 5 is out of operations
- Repairs expected in April/May





 Plans to start single-station operations in May

