

CS1 Observations

- Since 21/5 many tests before BG/L shutdown
 - Autocorrelation dips
 - Long baseline tests
 - Interference issues
 - Antenna Beam model







CS1 Status

- Stations
 - CS008 LBA_10 beamlet problem
 - Solved: reloaded image RSP2 board (old version)
 - - Modem replaced; pending final test but probably ok now







CS1 Status

- Network
 - + Lightpath LOFAR Amsterdam
 - 10 Gbps line functional
 - GRID storage not yet accessible awaiting configuration A'dam







CS1 Status

- CEP
 - + Lifs002 bad disk cable connection
 - Solved; no data lost
 - Mo 16/6 BG/L switched off
 - Only software correlations until BG/P operational
 - Max 1Gbps station connections until new switches arrived





