## SE607 Status update

A.O.Henrik Olofsson

Onsala rymdobservatorium...





ILT-TO f2f Hoofdorp 6-7 Nov. 2019

Google

2019 Google, TerraMetrics, Images © 2019 Aerodata International Surveys, Lantmäteriet/Metria, Maxar Technologies, Données cartographiques © 2019 Chili Conditions Envoyer des commentaires

## Some events since last meeting :

- SPUs broken Sep-18, Jun-19, Aug-19
- Fence reinforced with planks Sep/Oct-18 (image)
- LBA ground flattening Nov-18 (image)
- 3 long power cuts (LCU UPS lasts 34 min) of which one planned
- 9 transient power cuts (majority in August)
- A handful of LBA antenna down/strap replacements
- Installation of SETI computers in April 2019
  - one head-node, four data-nodes to come
  - collab with Berkeley, funded by Breakthrough Listen
- Astron maintenance visit Sep-19 (Henri & Lute)
  - 10 LBA + 1 HBA FE replaced
  - 1 faulty TBB repaired
  - 4 SPU boards replaced
  - Large number of fans replaced







## Lastly, what happened with the electric fence issue?

- Status quo !

- Took a TBB dump in September but all fences next to station were off at the time (cows had been moved seaside of the 20 m antenna where we also have electric fences)

- So still no dump where both the N-S arm west of field, and the E-W arm north of field are active

## Also RFI related :

- the new visitor centre is moving forward, will have solar panels (and LEDs of course), dialogue has been initiated with supplier to test for RFI