

LOFAR documents

LOFAR related documents. Many have been used in the CDR of May 2007. These documents probably reflect the most up-to-date view of the system, though some parts may have been obsoleted again. many of these documents can also be found in the LOFAR document Server.

General

- [LOFAR ADD](#)
- [LOFAR paper](#) (M. de Vos, A.W. Gunst, & R. Nijboer. "The LOFAR telescope: System Architecture and Signal Processing" in Proceedings of the IEEE, Special Issue "Advances in Radio Telescopes", Nov 2009)

WAN

- [LOFAR WAN ADD](#)

Station

- [Station ADD](#)
- [LBA ADD](#)
- [RCU signal analysis](#)
- [RSP firmware functional description](#)
- [Clock synchronisation description](#)

CEP

- [CEP ADD](#)
- [OLAP SDD](#)
- [Calibration implementation](#)
- [BBS SDD](#)
- [MAC ADD](#)
- [SAS SDD](#)
- [SHM ADD](#)
- [Harm Paas' Bootleg system document \(restricted\)](#)

Pipelines

Beam Formed Pipeline Checklist (EXCEL & PDF):

- [BF Pipeline Checklist v0.13 EXCEL \(May 12, 2010\)](#)
- [BF Pipeline Checklist v0.13 PDF \(May 12, 2010\)](#)

- [BF Pipeline Checklist v0.12 EXCEL \(Apr 21, 2010\)](#)
- [BF Pipeline Checklist v0.12 PDF \(Apr 21, 2010\)](#)
- [BF Pipeline Checklist v0.11 EXCEL \(Apr 7, 2010\)](#)
- [BF Pipeline Checklist v0.11 PDF \(Apr 7, 2010\)](#)
- [BF Pipeline Checklist v0.10 EXCEL \(Mar 24, 2010\)](#)
- [BF Pipeline Checklist v0.10 PDF \(Mar 24, 2010\)](#)
- [BF Pipeline Checklist v0.9 EXCEL \(Mar 10, 2010\)](#)
- [BF Pipeline Checklist v0.9 PDF \(Mar 10, 2010\)](#)
- [BF Pipeline Checklist v0.8 EXCEL \(Feb 24, 2010\)](#)
- [BF Pipeline Checklist v0.8 PDF \(Feb 24, 2010\)](#)
- [BF Pipeline Checklist v0.7 EXCEL \(Feb 10, 2010\)](#)
- [BF Pipeline Checklist v0.7 PDF \(Feb 10, 2010\)](#)
- [BF Pipeline Checklist v0.6 EXCEL \(Jan 28, 2010\)](#)
- [BF Pipeline Checklist v0.6 PDF \(Jan 28, 2010\)](#)
- [BF Pipeline Checklist v0.5 EXCEL \(Jan 13, 2010\)](#)
- [BF Pipeline Checklist v0.5 PDF \(Jan 13, 2010\)](#)
- [BF Pipeline Checklist v0.4 EXCEL \(Dec 16, 2009\)](#)
- [BF Pipeline Checklist v0.4 PDF \(Dec 16, 2009\)](#)
- [BF Pipeline Checklist v0.3 EXCEL \(Nov 18, 2009\)](#)
- [BF Pipeline Checklist v0.3 PDF \(Nov 18, 2009\)](#)
- [BF Pipeline Checklist v0.2 EXCEL \(Nov 17, 2009\)](#)
- [BF Pipeline Checklist v0.2 PDF \(Nov 17, 2009\)](#)
- [BF Pipeline Checklist v0.1 EXCEL \(Nov 5, 2009\)](#)
- [BF Pipeline Checklist v0.1 PDF \(Nov 5, 2009\)](#)

DataFormats

- [Description of the Measurement Set \(MS2\) format for LOFAR 0.5 \(Feb 2008\)](#)
- [Description of the Measurement Set \(MS2\) format for LOFAR 0.6 \(Feb/Mar/Apr 2010\)](#) *DRAFT*
- [Interface control documents for LOFAR data products](#)

Archive

- [LOFAR Archive and Reprocessing Requirements](#)
- Instructions how to [install gLite on Ubuntu](#) and tune the network for GRID access.

From:
<https://www.astron.nl/lofarwiki/> - **LOFAR Wiki**

Permanent link:
https://www.astron.nl/lofarwiki/doku.php?id=public:documents:lofar_documents&rev=1273687152

Last update: **2010-05-12 17:59**

