


# Array Status



## Current Status:

- 38 operational NL stations
- 24 CSs
- 14 RSs
- 8 ISs
- NL stations TBB memory upgrade installation RS started: 3 done, 11 to go (in combination with cabinet cleaning)
- UK608 maintenance visit Sep 2-6
- SE607 is next, but will be done by Onsala personal
- Heat exchanger problem RS508

[www.astron.nl/radio-observatory/astronomers/current-status](http://www.astron.nl/radio-observatory/astronomers/current-status)

# Network reconfiguration



- Re-configuration work went smoothly, until observations started
  1. Cobalt could not handle station network traffic (imbalance in traffic over routers), although observations went well
  2. Network configuration (routing) in front of BG/P + Cobalt re-balanced
  3. Re-balancing caused network traffic problems: too much cross-over traffic between switches
  4. Re-balancing act continues